Oil Field Environmental Incident Summary

Responsible Party: CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: BONNEY 6-3H

Field Name: JIM CREEK Well File #: 31195

Date Incident:12/14/2015Time Incident:13:20Facility ID Number:County:DUNNTwp:145Rng:96Sec:3Qtr:

Location Description: snow covered hayfield

Submitted By: Todd Senescall Received By:

Contact Person: Ben Lemieux

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Other - Described Above Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units
Oil 5 Gallons 5 Gallons 5 gallons

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 1/4/2016 Clean Up Concluded: 12/14/2015

Risk Evaluation:

fire

Areal Extent:

A 175 X 150' area of snow covered hayfield was lightly misted

Potential Environmental Impacts:

topsoil, vegetation

Action Taken or Planned:

Misted snow was scraped off and placed in flare pit, well choked back. Confirmation sampling will be done to determine if cleanup is adequate.

Wastes Disposal Location:

Agencies Involved: Bill Suess, NDDH

Tamara Cook, NDIC Inspector - notified CLR of the release

Updates

Date: 12/15/2015 Status: Reviewed - Follow-up Required Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release impacted areas off location. Followup is required.

Date: 12/29/2015 Status: Inspection Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 10:35. 10 degrees F, cloudy, NW wind 0-5 mph. Walked the area and took photos. It appeared that the release originated from the flare stack on the SW corner of the well pad and sprayed oil toward the SE, with a majority of the impact remaining on the well pad. It appeared that an area (approximately 200 square feet) off the well pad and outside of the fencing had some residual petroleum staining on the current snow cover.

More followup needed.